

CALL US: (800) 380-1718

Search

DR1500 Revision History

EPROM REV	VALID CHECKSUM	COMMENTS	ECO#/DATE ENGINEER	PROMPT CODE REV
145.100	D014	Added new features	C-002.1 / 1.Feb.99 Tom Hall	P145_100
145.130	0611	Limited production ship to fix ring debounce	Tom Hall	P145_100
150.263	283D	Added new features and corrected bugs in existing features	C-8-B / 26.Jul.01 Tom Hall	P150_256
150.266	111F	Limited production ship to fix ring debounce	Tom Hall	P150_256
150.274	2D77	Added	C-9-A / 8.Oct.03	P150_274

		attenuator *65# command Added 80 min. flash memory	Tom Hall	
160.004	6093	Limited production ship for sync messages using Accutime 200 GPS & DCC units	Tom Hall	P160_004
150.278	1A7B	80 min bug fix	C13 / 9.Jul.04 Tom Hall	P150_274
ASCII1 1.60.4.8.3.3	FE7F 65151	Digital down load stuff	E-Mail / 6.Aug.04 Tom Hall	P160_004
1.60.4.10.17.4 SEC3	F6AC 63148	Go live fix, security code fix * key ignored entering security code	E-Mail / 18.Oct.04 Tom Hall	P160_004
1.60.5.1.27.2.4 AGC4	1644 05700	Audio, auto level bug fix	E-Mail / 2.Feb.05	P160_004
1.60.5.5.15.1 Resp.4	8591 34193	*220#command, for Maryland, chart. Stores tele. response mode in nov Ram <prompts silent>	E-Mail / 6.Jun.05 Tom Hall	P160_004
1.60.5.9.5.1	0008 00008	80 to 40 min, D.D. to analog trim length fix	5.Sep.05 Tom Hall	P160_004

sections in
“frames”

1.60.6.2.28.1	4196 16790	Relax code to see different flash mem. IC's as valid	E-Mail / 9.Mar.06 Tom Hall	P160_004
1.60.6.4.4.1	2BE1 11233	Added code & prompts for TCM1 control	E-Mail / 5.Apr.06 Tom Hall	P160_005
160.6.9.6.51	69E1 27105	Synchronized message “echo” bug fix	C16-A / 13.Sep.06 Tom Hall	160_005
160.7.4.3.51	5F65 24421	Combine 160.6.4.4.1 & 160.6.9.6.51 for Penn. TCM order <Added synch fix>	E-Mail / 5.Apr.07 Tom Hall	160_005
160.7.5.4.51	5FF9 24569	Combine 160.7.4.3.51 & 160.7.4.25.51 <Added EAS fix>	E-Mail / 4.May.07 Tom Hall	160_005
161.7.5.23.2	7132 28978	Code for new flash mem., fixed mess. Stop when CLK updates	E-Mail / 30.May.07 Tom Hall	160_005
161.7.6.29.1	F548 62792	Added DTMF tone for Platinum Added 2 second delay for RC200	E-Mail / 22.Aug.07 Tom Hall	160_005
161.8.1.11.1	F580	Change timeout for digital	Tom Hall	160_005

download from
10 sec to 60 sec

Site Links

About

Products

Contact

Where To Buy

News

Featured Products

Highway Advisory Radio

NC300 Portable Traffic Analyzer

Distance Measurement

Flashing Beacons

Latest M.H. Corbin News

NC350 BlueStar Portable Traffic Analyzer available starting October 1st

M. H. Corbin is now ISO 9001:2008 Certified

M. H. Corbin Unveils New Website Design

NC300 Traffic Counter and Highway Data Management Software Release

Aquisition of Vaisala's non-weather traffic products