

NiteStar DMI Technical Update

Apr 26, 2013

Dear Sirs:

MH Corbin has identified a problem with the NiteStar DMI OBDII interface adapter (P/N: 70004178) that applies to 2013 model year Chevrolet, GM, and Ford vehicles. When using the adapter, distances reported by the DMI will be much shorter than actual distances traveled.

We are in the process of researching a solution.

This issue does not occur when using the SS-10 electronic interface (P/N: 70004094).

Until we have resolved the problem, MH Corbin recommends that customers of 2013 Chevrolet, GM, and Ford vehicles utilize the SS-10 module and not the OBD-II adapter.

Sincerely,



Alex Herring
MH Corbin, Inc.